

**Projekat za  
Čišćenje**

Nivo prioriteta:

**1****P= 19187 m<sup>2</sup>**Status: **Projekat dat donatoru / na tenderu**Investitor: **EU 2016****Dobrenica - Dubravica Mrdja****4****ID\_ 6730**

**LOKACIJA** Dobrenica - Dubravica Mrdja 4  
nalazi se oko 10,00 km juzno  
od mjesta Bihac

**FEDERACIJA BiH**Kanton: **UNSKO SANSKI**Općina/Opština: **Bihac**Lokalna zajednica: **Bihac gradska zona**

Nivo ugroženosti zajednice:

**Visoki**

Nivo koristi:

**I**

Nivo opasnosti:

**VISOKI**

Datum projekta:

**01.07.2016**

# OBRAZLOZENJE PROJEKTA

## 1. SOCIOEKONOMSKI UTICAJ

Predmetna lokacija je djelom sumsko područje koje se prije rata koristilo za sjecu ogrijevnog drveta, a djelom poljoprivredno zemljište. Pored lokacije prolazi put koji je u svakodnevnoj upotrebi. Provedjenjem operacija ciscenja na ovoj lokaciji stvorili bi se uvjeti za korištenje zemljišta u poljoprivredne svrhe a sumski odjeli bi se koristili od strane Unsko-sanskih suma za sjecu i posumljavanj. Takodjer bi se stvorili uslovi za sigurno korištenje lokalnog puta.

Broj neposredno ugroženih osoba i povremenih korisnika:	<b>30</b>
Broj korisnika nakon realizacije projekta:	<b>50</b>

## 2. PRIORITETIZACIJA

### NIVO OPASNOSTI

**V - VISOKI**

Lokacije za koje postoje indicije o postojanju mine PROM. Indicije podrazumjevaju evidentirane minske nesrece, prihvatljive zapisnike ili vjerodostojne svjedoke.

### NIVO KORISTI: I

#### KRITERIJ

##### H.1.4 EKONOMSKI RESURSI

Deminiranje poljoprivrednog zemljišta, odjela suma ogrijevnog drveta i drugih prirodnih resursa neophodnih za egzistenciju lokalnog stanovništva u ugroženim zajednicama.

## KARAKTERISTIKE TERENA

Vrsta okruzenja:	<b>Seosko</b>
Vegetacija:	<b>Suma Zbunje</b>
Zagadjenost:	<b>Metalni otpad Panjevi</b>
Vrsta tla:	<b>Glina Kamenjar</b>
Nagib:	<b>Blagi uspon Veliki uspon</b>
Tvrdoća tla:	<b>Srednje tvrdoće Tvrdo</b>

## PRIJEDLOG OPERACIJA I MOGUCIH METODA RADA

---

Metoda rada:	<b>Manuelno</b>
Dubina uklanjanja MES-a:	<b>Standardna</b>
Mogucnost spaljivanja:	<b>Ne</b>
Postojanje fortifikacijskih objekata:	<b>Da</b>
Broj kuca:	

## FOTOGRAFIJA KANDIDOVANOG PROJEKTA

---



Fotografisano sa tacke Y 5 571 869 X 4 958 328 pod uglom od 293°  
a pravac fotografisanja od tacke oznacen je na karti strelicom.

# Mine Clearance Project

## Dobrenica - Dubravica Mrdja 4

**ID\_6730**



Location: Dobrenica - Dubravica Mrdja 4  
is situated approx. 10.00 km south  
of Bihać

### FEDERACIJA BiH

Canton: **UNSKO SANSKI**

Municipality: **Bihać**

Local community: **Bihać gradska zona**

Level of priority:

**1**

**A= 19187m<sup>2</sup>**

Status: **Project given to a donor/tender**

Investor: **EU 2016**

Level of Impact in community: **High**

Level of Use:

**I**

Threat Level:

**HIGH**

Project date:

**01.07.2016**

## PROJECT DESCRIPTION

---

### 1. SOCIOECONOMIC IMPACT:

The subject location is partly forest area that had been used before the war for cutting firewood, and partly as agricultural land. A road that is used daily runs along the subject location. Completion of the mine clearance operations at this location would provide conditions for use of land for agricultural purposes, while the forested parts would be used by the Una-Sana forest management company for cutting wood and for forestation. Also, it would provide for safe use of the local road.

Number of directly impacted persons and occasional users: **30**

Number of users after project implementation: **50**

### 2. PRIORITISATION:

#### THREAT LEVEL

**H - HIGH**

There are indications of PROM mines on the location. Indications mean that there is location available data on mine incidents/accidents, minefield records or reliable witnesses

#### LEVEL OF USE: I

##### CRITERIA

**H.1.4 - ECONOMIC RESOURCES**

Demining of agricultural land, parts of forests with firewood and other natural resources necessary for the livelihood of local population in impacted communities

## FIELD CHARACTERISTICS

---

Type of environment:	<b>Rural</b>
Vegetation:	<b>Forest , Bushes</b>
Contamination:	<b>Metal debris , Trunks</b>
Soil type:	<b>Clay , Rocky ground</b>
Slope:	<b>Mild , Steep</b>
Soil hardness:	<b>Medium , Hard</b>

### PHYSICAL OBSTACLES:

## PROPOSAL FOR OPERATIONS AND POSSIBLE WORK METHODS

Work methods:	<b>MANUAL</b>
Depth of EOD removal:	<b>Standard</b>
Possibility of burning:	<b>No</b>
Presence of fortification facilities:	<b>Yes</b>
Number of houses:	

## PHOTOGRAPHY OF PROPOSED PROJECT



Photo taken from the point Y 5 571 869 X 4 958 328 under the angle of 293 degrees, direction marked on the map with an arrow.



## LEGENDA

- |   |                    |   |                       |
|---|--------------------|---|-----------------------|
|  | SUMNJIVA POVRŠINA  |  | TRAJNO OBILJEŽAVANJE  |
|  | RIZIČNA POVRŠINA   |  | MJESTO FOTOGRAFISANJA |
|  | OČIŠĆENA POVRŠINA  |   |                       |
|  | TEHNIČKO IZVIĐANJE |   |                       |



ID 6730

© 2016 Google

Image © 2016 CNES / Astrium

Google earth

2012

Imagery Date: 5/28/2016 44°46'05.95" N 15°54'15.21" E elev 387 m eye alt 1.60 km