

# Projekat za Tehničko izviđanje

Nivo prioriteta:

**1****P= 73622m<sup>2</sup>**Status: **Projekat dat donatoru / na tenderu**Investitor: **EU 2016**

## Milino Selo - Borice

**ID\_ 10293**

**LOKACIJA** Milino Selo - Borice  
nalazi se oko 10.00km jugozapadno  
od mjesta Lukavac

### FEDERACIJA BiH

Kanton: **TUZLANSKI**Općina/Opština: **Lukavac**Lokalna zajednica: **Milino Selo**Nivo ugroženosti zajednice: **Srednji**Nivo koristi: **I**Nivo opasnosti: **VISOKI**Datum projekta: **05.09.2016**

# OBRAZLOZENJE PROJEKTA

---

## 1. SOCIOEKONOMSKI UTICAJ

Tehnickim izvidjanjem predmetne lokacije uklonice se sumnja na postojanje mina i NUS-a sa poljoprivrednog zemljišta kao i sa zemljišta orbaslog borovom, hrastovom i bukovom sumom. Predmetnu površinu mjestani su prije rata koristili manjim djelom u poljoprivredne svrhe a vecim djelom za sjecu ogrevnog drveta i za branje sumskih plodova. Nakon tehnickog izvidjanja povratnici planiraju izvršiti sanaciju pristupnog puta do parcela i ponovno pokrenuti eksploataciju drveta za ogrev.

Broj neposredno ugroženih osoba i povremenih korisnika: **20**

Broj korisnika nakon realizacije projekta: **50**

## 2. PRIORITETIZACIJA

### NIVO OPASNOSTI

**V - VISOKI**

Područje je bilo između linija konfrontacije, zemljište se ne koristi, postoje zapisnici o minskim poljima i/ili postoji ucesnik ili vjerodostojan svjedok miniranja i vidljivi tragovi moguće minske opasnosti.

### NIVO KORISTI: **I**

#### KRITERIJ

##### **H.1.4 EKONOMSKI RESURSI**

Deminiranje poljoprivrednog zemljišta, odjela suma ogrijevnog drveta i drugih prirodnih resursa neophodnih za egzistenciju lokalnog stanovništva u ugroženim zajednicama.

---

## KARAKTERISTIKE TERENA

Vrsta okruženja:	Seosko
Vegetacija:	Trava Pojedinacno drvece Suma Zbunje
Zagadjenost:	Panjevi Smece
Vrsta tla:	Zemlja Kamenjar
Nagib:	Blagi uspon Veliki uspon
Vodeni tokovi:	Potok
Tvrdoća tla:	Mekano Srednje tvrdoce

---

## PRIJEDLOG OPERACIJA I MOGUĆIH METODA RADA

Metoda rada:	Manuelno
Dubina uklanjanja MES-a:	Standardna
Mogućnost spaljivanja:	Ne
Postojanje fortifikacijskih objekata:	Ne
Broj kuća:	

## FOTOGRAFIJA KANDIDOVANOG PROJEKTA

---



Fotografisano sa tacke Y- 6 533548.00 X - 4933609.00 pod uglom od 265°, a

# Technical Survey Project

## Milino Selo - Borice

**ID\_10293**



Location: Milino Selo - Borice  
is situated approx. 10.00 km southwest  
Lukavac

### FEDERACIJA BiH

Canton: **TUZLANSKI**

Municipality: **Lukavac**

Local community: **Milino Selo**

Level of priority:

**1**

A= **73622m<sup>2</sup>**

Status: **Project given to a donor/tender**

Investor: **EU 2016**

Level of Impact in community: **Medium**

Level of Use:

**I**

Threat Level:

**HIGH**

Project date:

**05.09.2016**

## PROJECT DESCRIPTION

---

### 1. SOCIOECONOMIC IMPACT:

Technical survey of subject location would eliminate mine and UXO danger from agricultural land as well as from land overgrown with pine, oak and beech forest. Before the war, subject location was used partially in agricultural purposes and mostly for cutting firewood and picking forest fruits. After operations of technical survey, returnees planned to recover access road towards plots and to restart exploitation of wood.

Number of directly impacted persons and occasional users: **20**

Number of users after project implementation: **50**

### 2. PRIORITISATION:

#### THREAT LEVEL

**H - HIGH**

Area was between confrontation lines; area is disused; there are minefield records and/or participant or witness of mining and visible traces of possible mine risk

#### LEVEL OF USE: **I**

##### CRITERIA

**H.1.4 - ECONOMIC  
RESOURCES**

Demining of agricultural land, parts of forests with firewood and other natural resources necessary for the livelihood of local population in impacted communities

## FIELD CHARACTERISTICS

---

Type of environment:	<b>Rural</b>
Vegetation:	<b>Grass , Wooded sparse , Forest , Bushes</b>
Contamination:	<b>Trunks , Garbage</b>
Soil type:	<b>Soil , Rocky ground</b>
Slope:	<b>Mild , Steep</b>
Water currents:	<b>Creek</b>
Soil hardness:	<b>Soft , Medium</b>

### PHYSICAL OBSTACLES:



## PROPOSAL FOR OPERATIONS AND POSSIBLE WORK METHODS


Work methods:	<b>MANUAL</b>
Depth of EOD removal:	<b>Standard</b>
Possibility of burning:	<b>No</b>
Presence of fortification facilities:	<b>No</b>
Number of houses:	

## PHOTOGRAPHY OF PROPOSED PROJECT



Photo taken from the point Y- 6 533548.00 X - 4933609.00 under the angle of 265 degrees, direction marked on the map with an arrow.





PRIPREMA I ŠTAMPA BHMAC SARAJEVO

LEGENDA	
	SUMNJIVA POVRŠINA
	RIZIČNA POVRŠINA
	OČIŠĆENA POVRŠINA
	TEHNIČKO IZVIĐANJE
	TRAJNO OBIJEŽAVANJE
	MJESTO FOTOGRAFISANJA






Image © 2016 CNES / Astrium  
© 2016 Google



2003

Datumi slika: 22/5/2016 44°32'30.44" S 18°24'59.95" I podizanje 285 m visina pogleda 1.41 km