


**Projekat za
Čišćenje**

Nivo prioriteta:

2**P= 2005 m²**Status: **Projekat gotov, ceka donatora**Investitor: **NONE****Dio trase vodovoda u Glodima****ID_ 54770**

LOKACIJA Dio trase vodovoda u Glodima
nalazi se oko 17.00 km jugozapadno
od mjesta Zvornik

REPUBLIKA SRPSKA

Kanton:

Općina/Opština: **Zvornik**Lokalna zajednica: **Glodi**

Nivo ugroženosti zajednice:

Niski

Nivo koristi:

I

Nivo opasnosti:

SREDNJI

Datum projekta:

02.08.2016

OBRAZLOZENJE PROJEKTA

1. SOCIOEKONOMSKI UTICAJ

Izviđana lokacija je poljoprivredno i šumsko zemljište u vlasništvu povratnika iz sela Glodi. Udaljeno je od najbližih kuća sela Glodi oko 200 metara. U prijeratnom periodu stanovništvo je predmetnu lokaciju koristilo za ispašu stoke i sječu ogrevnog drveta. Lokacija obuhvata dio trase vodovoda koja se treba izgraditi za potrebe povratnika u selo Glodi. Zbog minske opasnosti zemljište se ne koristi ni u kakve svrhe. Neposredno okruženje koriste povratnici iz okolnih sela koji se svojim aktivnostima dovode u opasnost od mina. Čišćenjem predmetne lokacije eliminisao bi se rizik od mina, omogućila bi se lokalnom stanovništvu sječa ogrevnog drveta, i otklonila bi se svakodnevna minska opasnost po lokalno stanovništvo.

Broj neposredno ugroženih osoba i povremenih korisnika:

10

Broj korisnika nakon realizacije projekta:

15

2. PRIORITETIZACIJA

NIVO OPASNOSTI

S - SREDNJI

Područje je bilo između linija konfrontacije, zemljište se ne koristi, nema zapisa o postojanju minskih polja, postoje određeni tragovi i informacije koje upućuju na moguću minsku opasnost

NIVO KORISTI: I

KRITERIJ

H.1.2 INFRASTRUKTURA

Deminiranje radi obnove i rekonstrukcije objekata infrastrukture kao što su: trasa puteva, elektromreža, vodovod, gasne i telefonske instalacije sa pratećim sadržajima i sa propisanim zaštitnim pojasom, kao i sanacija groblja i drugih sakralnih objekata.

KARAKTERISTIKE TERENA

Vrsta okruženja:

Seosko

Vegetacija:

Trava Pojedinacno drvece

Zagadjenost:

Panjevi

Vrsta tla:

Zemlja Glina

Nagib:

Blagi uspon Veliki uspon

Tvrdoća tla:

Mekano Srednje tvrdoće

Fizicke prepreke:

Ne postoje fizičke prepreke.

PRIJEDLOG OPERACIJA I MOGUĆIH METODA RADA

Metoda rada:	Manuelno
Dubina uklanjanja MES-a:	Standardna
Mogućnost spaljivanja:	Ne
Postojanje fortifikacijskih objekata:	Ne
Broj kuca:	0

FOTOGRAFIJA KANDIDOVANOG PROJEKTA



Fotografisano sa y=6584105 x=4909072 pod uglom od 164 stepeni a pravac fotografisanja od ta~ke ozna~en je na karti strelicom.

Mine Clearance Project

Dio trase vodovoda u Glodima

ID_54770



Location: Dio trase vodovoda u Glodima
is situated approx. 17.00 km southwest
Zvornik

REPUBLIKA SRPSKA

Municipality: **Zvornik**

Local community: **Glodi**

Level of priority:

2

A= **2005m²**

Status: **Project prepared,
waiting for a donor**

Investor: **NONE**

Level of Impact in community: **Low**

Level of Use: **I**

Threat Level: **MEDIUM**

Project date: **02.08.2016**

PROJECT DESCRIPTION

1. SOCIOECONOMIC IMPACT:

Surveyed area is agricultural and forest area in property of returnees of village Glodi. It is 200 meters away from the nearest houses. In the prewar period the population used this location for cattle grazing and cutting firewood. Location includes a part of waterfall route which should be built for needs of returnees from village Glodi. Due to mine risk the area is not used in any purpose. The immediate surrounding is used by returnees from local villages that doing their activities put themselves in danger. Clearance of this location would eliminate the mine risk, the cutting of firewood would be enabled and daily mine threat would be eliminated.

Number of directly impacted persons and occasional users: **10**

Number of users after project implementation: **15**

2. PRIORITISATION:

THREAT LEVEL

M - MEDIUM

Area was between confrontation lines; area is disused; there are no minefield records; there are indication and certain traces that indicate possible mine risk

LEVEL OF USE: **I**

CRITERIA

H.1.2 -

INFRASTRUCTURE

Demining for the reasons of rehabilitation and reconstruction of infrastructural facilities: roads, electricity networks, water pipelines, gas and telephone installations with accompanying facilities

FIELD CHARACTERISTICS

Type of environment:	Rural
Vegetation:	Grass , Wooded sparse
Contamination:	Trunks
Soil type:	Clay , Soil
Slope:	Mild , Steep
Soil hardness:	Soft , Medium

PHYSICAL OBSTACLES:

There are no physical obstacles.

PROPOSAL FOR OPERATIONS AND POSSIBLE WORK METHODS

Work methods:	MANUAL
Depth of EOD removal:	Standard
Possibility of burning:	No
Presence of fortification facilities:	No
Number of houses:	0

PHOTOGRAPHY OF PROPOSED PROJECT






Photo taken from the point $y=6584105$ $x=4909072$ under the angle of 164 degrees, direction marked on the map with an arrow.



ПРИПРЕМА И ШТАМПА: БХМАЦ КАНЦЕЛАРИЈА БАЊА ЛУКА
PREPARED AND PRINTED BY: BHMAC BANJA LUKA OFFICE



ID 54122

ID 54770

ID 54120

Image © 2016 CNES / Astrium
© 2016 Google



2003

Datumi slika: 22/10/2013 44°19'16.67" S 19°02'56.13" I podizanje 439 m visina pogleda 1.25 km